



 **EMSR884 - AOI12**  
**Earthquake in Venezuela**  
**CARABALLEDA**

**Situation as of 26/06/2026 15:10 UTC**  
Grading MONIT01 - Overview map 01



 Potentially affected population  
~ Not available

 Blocked road / interruption  
53 No.

 Temporary camp  
16 No.

Affected Built-up

 Built-Up  
2,770 No.

**Built Up Grading**


-  Destroyed
-  Damaged
-  Possibly damaged

**Facilities Grading**

-  Damaged
-  Possibly damaged

**Transportation Grading**

-  Main road, No visible damage
-  Local road, No visible damage
-  Track, No visible damage

-  Airfield and Heliport, Damaged
-  Airfield and Heliport, No visible damage

**Crisis Information**

-  Temporary camp
-  Blocked road / interruption

**General Information**

-  Area of Interest
-  Detail map
-  Not Analysed

**Hydrography**

-  Lake, River

**Event:** On 24 Jun 2026 22:05 UTC a 7.5M earthquake, preceded by a strong foreshock, occurred in Venezuela. The impact on population is deemed high at this stage, with low visibility on the extent of the damage. Copernicus EMS Rapid Mapping is requested to provide damage assessment emergency mapping.

**Data sources and analysis:** Pre-event image: Pléiades Neo © CNES (2026), distributed by Airbus DS (acquired on 05/01/2026 at 15:10 UTC and 08/01/2026 at 15:17 UTC, resolution 0.3 m).  
Post-event image: Legion © Vantor (2026), provided by European Space Imaging (acquired on 26/06/2026 at 15:10 UTC, resolution 0.5 m).  
This image is used as background image.  
All images are provided under COPERNICUS by the European Union and ESA, all rights reserved.

The thematic layer has been derived from post-event satellite image by means of visual interpretation.

This analysis has been supplemented by the social media.

Map produced by ITHACA released by SERTIT on the 02/07/2026.

Details on this activation and service conditions available through the QR code or at the link: <https://mapping.emergency.copernicus.eu/activations/EMSR884>



PROGRAMME OF THE  
EUROPEAN UNION



 0 0.5 1 2 km  
WGS 1982 UTM Zone 19N 1:45.000



- Built Up Grading**
- Destroyed
  - Damaged
  - Possibly damaged
- Transportation Grading**
- Main road, No visible damage
  - Local road, No visible damage
- Crisis Information**
- Blocked road / interruption
- General Information**
- Area of Interest
- Hydrography**
- Lake, River

**Event:** On 24 Jun 2026 22:05 UTC a 7.5M earthquake, preceded by a strong foreshock, occurred in Venezuela. The impact on population is deemed high at this stage, with low visibility on the extent of the damage. Copernicus EMS Rapid Mapping is requested to provide damage assessment emergency mapping.

**Data sources and analysis:** Pre-event image: Pléiades Neo © CNES (2026), distributed by Airbus DS (acquired on 05/01/2026 at 15:10 UTC and 08/01/2026 at 15:17 UTC, resolution 0.3 m). Post-event image: Legion © Vantor (2026), provided by European Space Imaging (acquired on 26/06/2026 at 15:10 UTC, resolution 0.5 m). This image is used as background image. All images are provided under COPERNICUS by the European Union and ESA, all rights reserved.

The thematic layer has been derived from post-event satellite image by means of visual interpretation.

This analysis has been supplemented by the social media.

Map produced by ITHACA released by SERTIT on the 02/07/2026.

Details on this activation and service conditions available through the QR code or at the link: <https://mapping.emergency.copernicus.eu/activations/EMSR884>



- Built Up Grading**
- Destroyed
  - Damaged
  - Possibly damaged
- Crisis Information**
- Blocked road / interruption

**Event:** On 24 Jun 2026 22:05 UTC a 7.5M earthquake, preceded by a strong foreshock, occurred in Venezuela. The impact on population is deemed high at this stage, with low visibility on the extent of the damage. Copernicus EMS Rapid Mapping is requested to provide damage assessment emergency mapping.

**Data sources and analysis:** Pre-event image: Pléiades Neo © CNES (2026), distributed by Airbus DS (acquired on 05/01/2026 at 15:10 UTC and 08/01/2026 at 15:17 UTC, resolution 0.3 m). Post-event image: Legion © Vantor (2026), provided by European Space Imaging (acquired on 26/06/2026 at 15:10 UTC, resolution 0.5 m). This image is used as background image. All images are provided under COPERNICUS by the European Union and ESA, all rights reserved.

The thematic layer has been derived from post-event satellite image by means of visual interpretation.

This analysis has been supplemented by the social media.

Map produced by ITHACA released by SERTIT on the 02/07/2026.

Details on this activation and service conditions available through the QR code or at the link: <https://mapping.emergency.copernicus.eu/activations/EMSR884>



**EMSR884 - AOI12**  
**Earthquake in Venezuela**  
**CARABALLEDA**

**Situation as of 26/06/2026 15:10 UTC**  
Grading MONIT01 - Detail map 04



- Built Up Grading**

  - Destroyed
  - Damaged
  - Possibly damaged

**Transportation Grading**

  - Main road, No visible damage
- Local road, No visible damage

**Crisis Information**

  - Blocked road / interruption

**General Information**

  - Area of Interest
  - Not Analysed

**Event:** On 24 Jun 2026 22:05 UTC a 7.5M earthquake, preceded by a strong foreshock, occurred in Venezuela. The impact on population is deemed high at this stage, with low visibility on the extent of the damage. Copernicus EMS Rapid Mapping is requested to provide damage assessment emergency mapping.

**Data sources and analysis:** Pre-event image: Pléiades Neo © CNES (2026), distributed by Airbus DS (acquired on 05/01/2026 at 15:10 UTC and 08/01/2026 at 15:17 UTC, resolution 0.3 m). Post-event image: Legion © Vantor (2026), provided by European Space Imaging (acquired on 26/06/2026 at 15:10 UTC, resolution 0.5 m). This image is used as background image. All images are provided under COPERNICUS by the European Union and ESA, all rights reserved.

The thematic layer has been derived from post-event satellite image by means of visual interpretation.

This analysis has been supplemented by the social media.

Map produced by ITHACA released by SERTIT on the 02/07/2026.

Details on this activation and service conditions available through the QR code or at the link: <https://mapping.emergency.copernicus.eu/activations/EMSR884>



**EMSR884 - AOI12**  
**Earthquake in Venezuela**  
**CARABALLEDA**

**Situation as of 26/06/2026 15:10 UTC**  
Grading MONIT01 - Detail map 05



- Built Up Grading**
- Destroyed
  - Damaged
  - Possibly damaged
- Facilities Grading**
- Possibly damaged
- Transportation Grading**
- Main road, No visible damage
  - Local road, No visible damage
  - Track, No visible damage
- Crisis Information**
- Blocked road / interruption
- General Information**
- Area of Interest
- Hydrography**
- Lake, River

**Event:** On 24 Jun 2026 22:05 UTC a 7.5M earthquake, preceded by a strong foreshock, occurred in Venezuela. The impact on population is deemed high at this stage, with low visibility on the extent of the damage. Copernicus EMS Rapid Mapping is requested to provide damage assessment emergency mapping.

**Data sources and analysis:** Pre-event image: Pléiades Neo © CNES (2026), distributed by Airbus DS (acquired on 05/01/2026 at 15:10 UTC and 08/01/2026 at 15:17 UTC, resolution 0.3 m). Post-event image: Legion © Vantor (2026), provided by European Space Imaging (acquired on 26/06/2026 at 15:10 UTC, resolution 0.5 m). This image is used as background image. All images are provided under COPERNICUS by the European Union and ESA, all rights reserved.

The thematic layer has been derived from post-event satellite image by means of visual interpretation.

This analysis has been supplemented by the social media.

Map produced by ITHACA released by SERTIT on the 02/07/2026.

Details on this activation and service conditions available through the QR code or at the link: <https://mapping.emergency.copernicus.eu/activations/EMSR884>



 **EMSR884 - AOI12**  
**Earthquake in Venezuela**  
**CARABALLEDA**

**Situation as of 26/06/2026 15:10 UTC**  
Grading MONIT01 - Detail map 06



**Built Up Grading**

- Destroyed
- Damaged
- Possibly damaged

**Crisis Information**

- Blocked road / interruption

**Hydrography**

- Lake, River

**Event:** On 24 Jun 2026 22:05 UTC a 7.5M earthquake, preceded by a strong foreshock, occurred in Venezuela. The impact on population is deemed high at this stage, with low visibility on the extent of the damage. Copernicus EMS Rapid Mapping is requested to provide damage assessment emergency mapping.

**Data sources and analysis:** Pre-event image: Pléiades Neo © CNES (2026), distributed by Airbus DS (acquired on 05/01/2026 at 15:10 UTC and 08/01/2026 at 15:17 UTC, resolution 0.3 m). Post-event image: Legion © Vantor (2026), provided by European Space Imaging (acquired on 26/06/2026 at 15:10 UTC, resolution 0.5 m). This image is used as background image. All images are provided under COPERNICUS by the European Union and ESA, all rights reserved.

The thematic layer has been derived from post-event satellite image by means of visual interpretation.

This analysis has been supplemented by the social media.

Map produced by ITHACA released by SERTIT on the 02/07/2026.

Details on this activation and service conditions available through the QR code or at the link: <https://mapping.emergency.copernicus.eu/activations/EMSR884>

Consequences within the AOI

|                    |                                               |  | LATEST IMPACT       |                           |
|--------------------|-----------------------------------------------|--|---------------------|---------------------------|
|                    |                                               |  | Unit of measurement | Imagery-based observation |
| Crisis information | Temporary camp<br>Blocked road / interruption |  | No.                 | 16                        |
|                    |                                               |  | No.                 | 53                        |

| Estimated population |                | Inhabitants                                                  | No. | Destroyed | Damaged | Possibly damaged* | Total affected** | Total in AOI |
|----------------------|----------------|--------------------------------------------------------------|-----|-----------|---------|-------------------|------------------|--------------|
| Assets               |                | Built-up                                                     |     |           |         |                   | NA               | ~ 330.000    |
|                      |                | Residential Buildings                                        | No. | 49        | 90      | 58                | 197              | 198          |
|                      |                | Other non-residential buildings                              | No. | 121       | 86      | 27                | 234              | 235          |
|                      |                | Unclassified                                                 | No. | 511       | 599     | 1.229             | 2.339            | 59.987       |
|                      | Transportation | Airfield runways                                             | ha  | 0         | 601,3   | 0                 | 601,3            | 601,3        |
|                      |                | Helipad                                                      | ha  | 0         | 0       | 0                 | 0                | 0,04         |
|                      |                | Highways                                                     | km  | 0         | 0       | 0                 | 0                | 5,2          |
|                      |                | Primary Road                                                 | km  | 0         | 0       | 0                 | 0                | 81,6         |
|                      |                | Secondary Road                                               | km  | 0         | 0       | 0                 | 0                | 29,8         |
|                      |                | Local Road                                                   | km  | 0         | 0       | 0                 | 0                | 446,0        |
|                      |                | Cart Track                                                   | km  | 0         | 0       | 0                 | 0                | 18,7         |
|                      | Facilities     | Settling Basin                                               | ha  | 0         | 0       | 0                 | 0                | 1,5          |
|                      |                | Breakwater                                                   | ha  | 0         | 0       | 0                 | 0                | 2,7          |
|                      |                | Power plant constructions                                    | ha  | 0         | 13,1    | 0                 | 13,1             | 13,1         |
|                      |                | Sport and recreation constructions                           | ha  | 0         | 5,3     | 0,8               | 6,1              | 25,9         |
|                      |                | Other civil engineering works not elsewhere classified       | ha  | 0         | 0       | 0                 | 0                | 2,0          |
|                      |                | Long-distance pipelines, communication and electricity lines | km  | 0         | 0       | 0                 | 0                | 10,5         |
|                      | Land use       | Forests                                                      | ha  |           |         |                   | 0                | 1.088,5      |
|                      |                | Shrub and/or herbaceous vegetation association               | ha  |           |         |                   | 0                | 1.832,8      |
|                      |                | Open spaces with little or no vegetation                     | ha  |           |         |                   | 0                | 101,2        |
|                      |                | Inland wetlands                                              | ha  |           |         |                   | 0                | 2,4          |
|                      |                | Other                                                        | ha  |           |         |                   | 0                | 3.627,2      |

\* Presence of damage proxies and proximity with destroyed/damaged asset  
\*\* Sum of all damage classes

**Disclaimer:**  
Full disclaimer and other helpful information available in the online manual:  
<https://mapping.emergency.copernicus.eu/about/rapid-mapping-manual/>  
© European Union / Copernicus Emergency Management Service

**Data Access:**  
All data displayed on the map(s), as well as Land Use - Land Cover layer(s), are available in the Crisis Information Package and the Base Layer Package (for reference data). The table above is available in editable format in the Crisis Information Package. All products and data are also available for download on the portal.

**Estimated Population:**  
Estimated population is based on Copernicus Global Human Settlement Layer (GHSL) dataset. Additional population datasets and analysis are available in the summary table.

**Data Sources:**  
Base Vector Layers: OpenStreetMap © OpenStreetMap contributors (2026); Wikimapia.org; GeoNames 2015; © EuroGeographics, © TurkStat. Source: European Commission – Eurostat/GISCO, 2024. Globe Land 30 (2010), Copernicus Global Land Service: Land Cover (2019).

Inset Maps: Natural Earth 2023; HydroLAKES 2016 by HydroSHEDS; © EuroGeographics, © TurkStat. Source: European Commission – Eurostat/GISCO, 2024.

Access to the portal

